

Model:	D9
Version:	V1.48
Issue date:	16 th Oct 2026
Type:	Public

New Features

-

Improvement:

- Fixed an issue where volume limit -15dB does not work
- Updated the power-on volume limit options list

Additional information

Firmware update instructions.

1. Turn off the power supply to the device (rear panel mains switch)
2. Install the update file on a FAT32 formatted USB drive (folder name must be 'D9' and content should include D9.bin)
3. Insert the USB drive to the 'UPDATE' USB socket on the rear panel of the device.
4. Push and hold the front panel standby button.
5. Turn on the power supply to the device (rear panel mains switch) while continuing to hold the standby button.
6. Release the standby button and the display will show 'upgrade processing'.
7. Allow the device to apply the software update. This may take a few seconds.
8. When update is complete, the device is ready to use.

Change history

V1.47

- Fixed an issue where changing PC USB playback from DSD to PCM would occasionally result in a short burst of noise
- Revise the name and options of the MQA menu.
- Fixed an issue where the PC USB button on the remote fails to activate the display.

V1.46

- Add MCU ID to menu option - Version

V1.44

- MQA default setting change to Full decode B
- Default source set to OPT1

V1.42

- Fix timeout bug of Display Options

V1.41

- Fix digital input clicks in Full decode B mode

V1.39

- Fix display off and display settings bug
- Fix USB HDD playback bug, increase track name length limit of USB HDD
- Add -15dB option to Power On limit

V1.39

- Fix minor GUI bug when you set the display to "Off"
- Fix scrolled track name bug of Bluetooth connection

V1.38

- First release