

Model:	9000Q
Version:	V1.42
Issue date:	28 th January 2026
Type:	Public

New Features

-

Improvement

- Fix volume recall bug
- Mute the unit briefly when changing filter settings.

Additional information

Firmware update instructions.

1. Turn off the power supply to the device (rear panel mains switch)
2. Copy the update file onto a FAT32 formatted USB drive (maximum 32GB, folder name must be '9000Q' and contents should be 9000Q.bin)
3. Insert the USB drive to the 'UPDATE' USB socket on the rear panel of the device.
4. Push and hold front panel standby button.
5. Turn on the power supply to the device (rear panel mains switch) while continuing to hold the standby button.
6. Release the standby button and the display will show 'upgrade processing'.
7. Allow the device to apply the software update. This may take a few minutes.
8. When update is complete, the device is ready to use.

Change history

V1.40

Change source menu to RED as selected
Power on limit volume setting bug
Headphone recall volume setting bug

V1.39

Add MCU ID in menu option
Fix volume setting (level and progress bar) bug
No digital output in rear case

V1.36

Add separate volume recall for headphones

V1.35

Add Volume Power On Recall feature - volume setting retention to each source
Add -15dB option to Volume Power on limit

V1.34

Fix Russian character bug

V1.33

Fix XMOS reset issue which may cause the sound loss of digital inputs

V1.31

Fix DPLL setting change interrupts the audio on other source

V1.29

First release version